


Bihl+Wiedemann / BW3490

AS-Interface emniyet modülü

Üretici ürün kodu: BW3490

Seri: AS-Interface



Bihl+Wiedemann BW3490 (BW3490), as-interface emniyet modülü. Emniyet girişleri: 6-8 x 2 channels; depending on configuration; Emniyet sinyali girişleri: OSSDs, complementary switch, floating contacts; Emniyet çıkışları: up to 2 release circuits, up to 2 x electronic safe outputs; depending on configuration.

TEKNİK ÖZELLİKLER

Emniyet girişleri	6-8 x 2 channels; depending on configuration
Emniyet sinyali girişleri	OSSDs, complementary switch, floating contacts
Emniyet çıkışları	up to 2 release circuits, up to 2 x electronic safe outputs; depending on configuration
Emniyet sinyali çıkışları	electronic safe outputs
Sensör beslemesi	AUX üzerinden
Aktüatör beslemesi	AUX üzerinden
ASi adresi	depending on configuration
Özel işlev	muting


Seçili üretici değerleridir; kaynakta belirtilen koşullar ve dipnotlar geçerlidir. Üretici görseli teslim edilen varyanttan farklı olabilir. Automation özeti orijinal dokümantasyonun yerine geçmez.

Bihl+Wiedemann / BW3490

ASi Safety I/O Module, IP67, M12, 6-8SI/2SO/16I/16O

Part/model code: BW3490

Series: AS-Interface



Bihl+Wiedemann BW3490 (BW3490): asi safety i/o module, ip67, m12, 6-8si/2so/16i/16o. Inputs Safety: 6-8 x 2 channels; depending on configuration; Safety signal inputs: OSSDs, complementary switch, floating contacts; Outputs Safety: up to 2 release circuits, up to 2 x electronic safe outputs; depending on configuration.

TECHNICAL HIGHLIGHTS

Inputs Safety	6-8 x 2 channels; depending on configuration
Safety signal inputs	OSSDs, complementary switch, floating contacts
Outputs Safety	up to 2 release circuits, up to 2 x electronic safe outputs; depending on configuration
Safety signal outputs	electronic safe outputs
Input voltage (sensor supply)	out of AUX
Output voltage (actuator supply)	out of AUX
ASi address	depending on configuration
Special function	muting

Selected manufacturer values; source conditions and footnotes apply. The manufacturer illustration may differ from the delivered variant. This Automation summary does not replace the original documentation.