

ReeR / MOSAIC MBPC

Endüstriyel emniyet bileşeni

Üretici ürün kodu: 1100150

Seri: MOSAIC



ReeR MOSAIC MBPC (1100150), endüstriyel emniyet bileşeni. Çalışma sıcaklığı (°C): - 10 ... 55; Sinyalizasyon: LEDs indication for operating status ve fault diagnosis; Bağlantılar: Removable terminal blocks, clamp contacts - PROFIBUS connect.

TEKNİK ÖZELLİKLER

Çalışma sıcaklığı (°C)	- 10 ... 55
Sinyalizasyon	LEDs indication for operating status ve fault diagnosis
Bağlantılar	Removable terminal blocks, clamp contacts - PROFIBUS connect
Depolama sıcaklığı (°C)	-20 ... +85
MSC konnektör dahil	Evet
MSC BUS bağlantısı	Evet
Alan veri yolu arayüzleri	PROFIBUS
Besleme (VDC)	24 ± 20%
Boyutlar Y×G×D (mm)	99 x 22,5 x 114
Koruma derecesi	IP20 for housing - IP2X for terminal block
Sabitlenme	35 mm DIN rail fastening according to EN 50022-35 standard

Seçili üretici değerleridir; kaynakta belirtilen koşullar ve dipnotlar geçerlidir. Üretici görseli teslim edilen varyanttan farklı olabilir. Automation özeti orijinal dokümantasyonun yerine geçmez.

ReeR / MOSAIC MBPC

Safety automation component

Part/model code: 1100150

Series: MOSAIC



ReeR MOSAIC MBPC (1100150): safety automation component. Operating temperature (°C): - 10 ... 55; Signalling: LEDs indication for operating status and fault diagnosis; Connections: Removable terminal blocks, clamp contacts - PROFIBUS connect.

TECHNICAL HIGHLIGHTS

Operating temperature (°C)	- 10 ... 55
Signalling	LEDs indication for operating status and fault diagnosis
Connections	Removable terminal blocks, clamp contacts - PROFIBUS connect
Storage temperature (°C)	-20 ... +85
MSC connector provided	Yes
Connection with MSC BUS	Yes
Fieldbus interfaces	PROFIBUS
Power supply (VDC)	24 ± 20%
Dimensions HxWxD (mm)	99 x 22,5 x 114
Degree of protection	IP20 for housing - IP2X for terminal block
Fastening	35 mm DIN rail fastening according to EN 50022-35 standard

Selected manufacturer values; source conditions and footnotes apply. The manufacturer illustration may differ from the delivered variant. This Automation summary does not replace the original documentation.