


Yılmaz Redüktör DR472.00 Paralel Milli Redüktör

TEMEL MODEL / DR472.00

DR472.00, D47 gövdesinde iki kademeli tahrik ve 50 mm delik milli çıkış sunar. Tahrik edilen milin yüzey durumu, özellikle eski bir ekipmana yeni redüktör takılırken kontrol edilmelidir. Aşınma veya korozyon bulunan bağlantıda yalnız nominal ölçüye güvenmeden milin mevcut durumunu tarif ederek uygun montaj koşullarını değerlendirebilirsiniz.



Resmî aile görseli

Doğrulanmış teknik referanslar

Model kodu	DR472.00
Gövde grubu	D47
Dişli yapısı	Paralel milli helisel
Kademe	2
Giriş bağlantısı	Direkt motor akupleli; motor seçimi gerekli
Çıkış / montaj	Standart delik milli (.00)
Standart kovan çapı (mm)	Ø50
Gövde grubu nominal torku (Nm, referans)	1.550

Milin güncel ölçümünü, kama durumunu ve yüzey fotoğrafını paylaşın.

Eski milin nominal etiketi montaj için yeterli mi?

Gerçek ölçüm ve yüzey kontrolü gerekir; aşınma nominal ölçüden sapmaya neden olabilir.


DR472.00 yenileme teklifinizi mevcut milin durumuyla birlikte inceleyelim.

Temel model: tahvil, motor/giriş bağlantısı ve montaj pozisyonu teyit edilir. Gövde torku referanstır; seçili takımın çıkış değeri değildir. Görsel aileye aittir; boyut ve motor değişebilir.

Yılmaz Redüktör DR472.00 Parallel-Shaft Gearmotor

BASE MODEL / DR472.00

DR472.00 offers two-stage transmission and a 50 mm hollow output in the D47 group. Check driven-shaft condition when fitting a new gearbox to older equipment. With wear or corrosion present, actual measurements and surface information are more useful than the original nominal dimension alone.



Official family visual

Verified technical references

Model code	DR472.00
Housing group	D47
Gear type	Parallel-shaft helical
Stages	2
Input connection	Directly motor-coupled; motor selection required
Output / mounting	Standard hollow output (.00)
Standard hollow bore (mm)	Ø50
Housing-group nominal torque (Nm, reference)	1550

Provide current shaft measurements, key condition and a surface photograph.

Is the old shaft's nominal dimension sufficient?

Actual measurement and surface inspection are needed because wear can change the fit.

Review your DR472.00 replacement enquiry with the existing shaft condition.

Base model: ratio, motor/input interface and mounting position require confirmation. Housing torque is a reference, not a configured output rating. Family image; exact size and motor may differ.