


Yılmaz Redüktör DR572.00 Paralel Milli Redüktör

TEMEL MODEL / DR572.00

DR572.00, D57 grubunda iki kademeli ve 60 mm standart delik milli motor-redüktördür. Katalogdaki 3.000 Nm gövde referansı, ön seçimde yük büyüklüğünü karşılaştırmak için kullanılır. Sık duruş yaşayan bir mekanizma için arızanın nedenini ve yükün değişimini açıklamanız, yeni seçimin yalnız eski modelin tekrarına dayanmasını önler.



Resmî aile görseli

Doğrulanmış teknik referanslar

Model kodu	DR572.00
Gövde grubu	D57
Dişli yapısı	Paralel milli helisel
Kademe	2
Giriş bağlantısı	Direkt motor akupleli; motor seçimi gerekli
Çıkış / montaj	Standart delik milli (.00)
Standart kovan çapı (mm)	Ø60
Gövde grubu nominal torku (Nm, referans)	3.000

Eski tahrikte görülen sorunu, yük değişimini ve çalışma saatlerini belirtin.

Yeni redüktör seçimi için arıza bilgisi yararlı mı?

Evet. Aşırı yük, yanlış montaj veya farklı işletme koşulları seçim ve kurulum kontrolünün kapsamını etkileyebilir.


DR572.00 teklifini arıza geçmişi ve güncel yük üzerinden değerlendirelim.

Temel model: tahvil, motor/giriş bağlantısı ve montaj pozisyonu teyit edilir. Gövde torku referanstır; seçili takımın çıkış değeri değildir. Görsel aileye aittir; boyut ve motor değişebilir.

Yılmaz Redüktör DR572.00 Parallel-Shaft Gearmotor

BASE MODEL / DR572.00

DR572.00 is a two-stage D57 gearmotor with a standard 60 mm hollow shaft. The 3,000 Nm housing reference supports preliminary load comparison. For a mechanism with repeated stoppages, describing failure history and changing loads helps avoid simply repeating the previous selection.



Official family visual

Verified technical references

Model code	DR572.00
Housing group	D57
Gear type	Parallel-shaft helical
Stages	2
Input connection	Directly motor-coupled; motor selection required
Output / mounting	Standard hollow output (.00)
Standard hollow bore (mm)	Ø60
Housing-group nominal torque (Nm, reference)	3000

Explain the previous problem, load changes and operating hours.

Does failure information help replacement selection?

Yes. Overload, installation issues or changed conditions can affect both selection and installation checks.

Assess DR572.00 against the failure history and current duty.

Base model: ratio, motor/input interface and mounting position require confirmation. Housing torque is a reference, not a configured output rating. Family image; exact size and motor may differ.