
Yılmaz Redüktör MR572 Ayaklı Helisel Redüktör

TEMEL MODEL / MR572

MR572, M57 gövdesinde iki kademeli ayaklı tahrik için 60 mm çıkış mili sunar. 120 mm mil boyu üzerinden bağlanacak ekipman ve şase yerleşimi kontrol edilebilir. Eski bir M50 veya farklı revizyonlu ürünün yerine seçim yapılacaksa model benzerliğine güvenmek yerine etiket ve ölçü karşılaştırmasıyla ilerlemek doğru siparişin temelidir.



Resmî aile görseli

Doğrulanmış teknik referanslar

Model kodu	MR572
Gövde grubu	M57
Dişli yapısı	Helisel
Kademe	2
Giriş bağlantısı	Direkt motor akupleli; motor seçimi gerekli
Çıkış / montaj	Ayak bağlantılı, dolu mil
Standart çıkış mili çap/boy (mm)	Ø60/120
Gövde grubu nominal torku (Nm, referans)	3.000

Değiştirilecek ürünün tam kodunu, seri numarasını ve bağlantı çizimini gönderin.

Eski gövde kodu yerine MR572 otomatik seçilir mi?

Hayır. Revizyon farkları, bağlantı geometrisi ve çalışma değerleri teyit edilmeden eşdeğerlik kurulmaz.


MR572 yenileme teklifini mevcut ürününüzün ölçüleriyle hazırlayalım.

Temel model: tahvil, motor/giriş bağlantısı ve montaj pozisyonu teyit edilir. Gövde torku referanstır; seçili takımın çıkış değeri değildir. Görsel aileye aittir; boyut ve motor değişebilir.

Yılmaz Redüktör MR572 Foot-Mounted Helical Gearmotor

BASE MODEL / MR572

MR572 offers a 60 mm output shaft for a two-stage foot-mounted drive in the M57 group. Its 120 mm shaft length helps assess the connected equipment. Replacing an older or differently revised model requires nameplate and dimensional comparison rather than relying on a similar model number.



Official family visual

Verified technical references

Model code	MR572
Housing group	M57
Gear type	Helical
Stages	2
Input connection	Directly motor-coupled; motor selection required
Output / mounting	Foot mounted, solid output shaft
Standard output shaft diameter/length (mm)	Ø60/120
Housing-group nominal torque (Nm, reference)	3000

Send the complete old code, serial number and connection drawing.

Does MR572 automatically replace an older housing code?

No. Revision, mounting geometry and operating values must be checked before establishing equivalence.

Prepare an MR572 replacement proposal against your existing unit.

Base model: ratio, motor/input interface and mounting position require confirmation. Housing torque is a reference, not a configured output rating. Family image; exact size and motor may differ.